

FIG. 1





FIG. 12






FIG. 3




FIG. 4

FIG. 4 is a schematic diagram of a mechanical assembly. It features a curved member 5, which appears to be a part of a larger structure. A central pivot point 7 is located on member 5. A long, thin, tapered member 8(4) is attached to the pivot point 7. A label L points to the tapered member 8(4).

FIG. 6




FIG. 7




FIG. 8




FIG. 9

